

Inspection Photos
Location Name: State 5-36
Location ID: 313027



Photo 1. Overview of location taken facing north. Annual weeds on location.




Photo 2. No bradenhead access apparent. Previous operator on location signs.

