

Inspection Photos

API: 071-07989

Operator: OGRIS OPERATING LLC

Inspection Date: 9/28/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07989 | Date: 9/28/2021

Inspection Photos



Photo 1. There is erosion along the access road near the location. Areas of erosion need to be repaired and stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07989 | Date: 9/28/2021

Inspection Photos



Photo 2. The erosion continues off the side of the road shown from previous photo. This area needs to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07989 | Date: 9/28/2021

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07989 | Date: 9/28/2021