

# Inspection Photos

API: 071-06435

Operator: OGRIS OPERATING LLC

Inspection Date: 9/28/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06435 | Date: 9/28/2021

## Inspection Photos



**Photo 1.** This area near the fence line consists of noxious weeds Canada thistle. The noxious weeds have not been controlled and are dispersing seed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06435 | Date: 9/28/2021



## Inspection Photos



**Photo 2.** Drone aerial photo facing west at the reclaimed road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06435 | Date: 9/28/2021



## Inspection Photos



**Photo 3.** View of canyon bottom shows noxious weeds (Scotch, Plumeless thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06435 | Date: 9/28/2021



## Inspection Photos



**Photo 4.** View of reclaimed road at west side toward the GE 28-13.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06435 | Date: 9/28/2021