

Inspection Photos
Location Name: Wailes 41-33 #1-X
Location ID: 320006



Photo 1 Well site. Equipment is approx. 250ft from residents home. Weeds on location.

Photo 2 Well head sign and weeds.

Inspection Photos
Location Name: Wailes 41-33 #1-X
Location ID: 320006



Photo 3 WEEDS

Photo 4 WEEDS

Inspection Photos
Location Name: Wailes 41-33 #1-X
Location ID: 320006



Photo 5 TNK BTRY



Photo 6 produced water tank.

Inspection Photos
Location Name: Wailes 41-33 #1-X
Location ID: 320006



Photo 7 TNK BTRY

Photo 8 facility Pic WEEDS

Inspection Photos
Location Name: Wailes 41-33 #1-X
Location ID: 320006



Colorado Oil and Gas Conservation Commission
39.92447, -104.54588, 1587.2m
Sep 27, 2021 1:57:49 PM




Colorado Oil and Gas Conservation Commission
39.9248, -104.54586, 1588.5m
Sep 27, 2021 1:58:20 PM

Photo 9 Separator, meter run and meter house. WEEDS

Photo 10 Facility pic WEEDS

Inspection Photos
Location Name: Wailes 41-33 #1-X
Location ID: 320006



Colorado Oil and Gas Conservation Commission
 39.92417, -104.54615, 1601.6m
 Sep 27, 2021 2:01:54 PM



Colorado Oil and Gas Conservation Commission
 39.92431, -104.54625, 1593.6m
 Sep 27, 2021 2:02:58 PM

Photo 11 meter calibration card.

Photo 12 unused equip: meter run has 2" bullplug installed not operational and in disrepair.