

# Inspection Photos

API: 071-09362

Operator: OGRIS OPERATING LLC

Inspection Date: 9/28/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09362 | Date: 9/28/2021

## Inspection Photos



**Photo 1.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09362 | Date: 9/28/2021

## Inspection Photos



**Photo 2.** Facing toward the well and pit which is lined and fenced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09362 | Date: 9/28/2021