

Inspection Photos
Location Name: Pintail PAD
Location ID: 454414



Colorado Oil and Gas Conservation Commission
 40.69911, -104.07056, 4876.2ft, 191°
 09/22/2021 15:18:16



Colorado Oil and Gas Conservation Commission
 40.7 - 104.06453, 4867.2ft, 311°
 09/22/2021 15:20:08

Photo 1 – Sign at Entrance

Photo 2 – Tank Battery

Inspection Photos
Location Name: Pintail PAD
Location ID: 454414



Colorado Oil and Gas Conservation Commission
40.69992, -104.06338, 4862.7ft, 248°
09/22/2021 15:22:34

Photo 3 – Wellheads



Colorado Oil and Gas Conservation Commission
40.64397, -104.06357, 176°
09/22/2021 15:24:30

Photo 4 – ECDs

Inspection Photos
Location Name: Pintail PAD
Location ID: 454414



Colorado Oil and Gas Conservation Commission
40.70101, -104.06428, 4858.7ft, 216°
09/22/2021 15:25:13

Photo 5 – Separators



Colorado Oil and Gas Conservation Commission
40.70008, -104.06425, 4869.8ft, 342°
09/22/2021 15:22:05

Photo 6 – Unused Pipe East of Tanks

Inspection Photos
Location Name: Pintail PAD
Location ID: 454414



Photo 7 – Unused Pipe and Metal Siding