

Inspection Photos  
Location Name: Shoveler PAD  
Location ID: 455365



Photo 1 – Sign at Entrance



Photo 2 – Tank Battery

**Inspection Photos**  
**Location Name: Shoveler PAD**  
**Location ID: 455365**



**Photo 3 – ECDs**



**Photo 4 – Separators**





**Inspection Photos**  
**Location Name: Shoveler PAD**  
**Location ID: 455365**



**Photo 5 – Wellheads**



**Photo 6 – Compressor**

Inspection Photos  
Location Name: Shoveler PAD  
Location ID: 455365



Photo 7 – Capacity Label missing



Photo 8 – Capacity Label missing