

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TBI PRODUCTION-67S96W /25SESW

Location ID: 324002



Photo #4967 from entrance to location.



Photo #4968 from entrance to location.


## Inspection Photos

Location Name: CAERUS PICEANCE LLC TBI PRODUCTION-67S96W /25SESW

Location ID: 324002



Photo #4949 No battery sign located at the tank battery.



SE coordinate of tank battery.

