

Inspection Photos
Location Name: Pete Montoya B #2
Location ID: 318386



Photo 1 WH sign

Photo 2 Dead weeds around WH

Inspection Photos
Location Name: Pete Montoya B #2
Location ID: 318386



Photo 3 Weeds around pump jack/location

Photo 4 Weeds around ancillary equip.

Inspection Photos
Location Name: Pete Montoya B #2
Location ID: 318386



Photo 5 Weeds around pump jack/location