


Inspection Photos
Location Name: SRC Williams Pad
Location ID: 445473



Lease road entrance sign



Production facility

Inspection Photos
Location Name: SRC Williams Pad
Location ID: 445473



Colorado Oil & Gas Conservation Commission
40.34644, -104.89707, 1430.3m, 210°
09/30/2021 13:15:14

Earth berm



Colorado Oil & Gas Conservation Commission
40.3463, -104.89714, 1439.7m, 186°
09/30/2021 13:15:24

Earth berm

Inspection Photos
Location Name: SRC Williams Pad
Location ID: 445473



Earth berm



Lube oil storage netting

Inspection Photos
Location Name: SRC Williams Pad
Location ID: 445473



Condensate tank sign



Condensate tank sign

Inspection Photos
Location Name: SRC Williams Pad
Location ID: 445473



Fiberglass tank sign