

Inspection Photos

Location Name: EP ROCKY MOUNTAIN LLC PUCKETT-66S95W /35SENW

Location ID: 335098



Photo #4980 from entrance to location.



Photo #4981 from entrance to location.

Inspection Photos

Location Name: EP ROCKY MOUNTAIN LLC PUCKETT-66S95W /35SENW

Location ID: 335098



Photo #4982 Glycol storage tank missing required information.



Photo #4983 Gauge hatch open.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources