



• Photo 1 –



- Photo 2 – Animal burrows on south side of oil tank battery



- Photo 3 – Animal burrows on southwest corner of oil tank battery



- Photo 4 – Recent earthwork along wester berm of oil tank battery



- Photo 5 – Recent earthwork, deep muddy tracks south of oil tank battery



- Photo 6 – Overgrown weeds on south produced water pit berm