

Final Reclamation Inspection

September 9th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 330563

Inspection Document #: 698400018

Weld County, CO

NESE Section 13 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name:Schmidt 32-13
Location ID: 330563



Photo 1. 2019 aerial imagery shows the well head and tank battery (north is up). Note: no well head access road (well was accessed via farm road). The tank battery is still in operation and is associated with API#123-11892.

Inspection Photos
Location Name:Schmidt 32-13
Location ID: 330563



Photo 2. Overview photo of well head and reference area taken west of well head, looking northeast. Photo shows ongoing landowner disturbance that was present prior to the well being PA.

Inspection Photos
Location Name:Schmidt 32-13
Location ID: 330563



Photo 3. North and East photos taken at ground level from middle of well head.

Inspection Photos
Location Name:Schmidt 32-13
Location ID: 330563



Photo 4. South and west photos taken at ground level from the middle of the well head.

Inspection Photos
Location Name:Schmidt 32-13
Location ID: 330563



Photo 5. Reference photo taken from the east corner of the well head, looking northeast.