

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Pic 1 tanks, open top tank does not have labels



Pic 2 open top tank does not have labels

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Pic 3 Open top tank has dead animals, and oil inside.




Pic 4 weeds uncontrolled on location.

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Pic 5



Pic 6 weeds unmanaged on location

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



**Pic 7 stained soil / mechanical issue with pumping unit
motor**