

Final Reclamation Inspection

September 2nd, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 330708

Inspection Document #: 701900094

Weld County, CO

NWSE Section 24 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Maxey 33-24
Location ID: 330708




Photo 1. 2021 aerial imagery of the tank battery, well pad and adjacent reference area (north is up).

Inspection Photos
Location Name: Maxey 33-24
Location ID: 330708




Photo 2. Overview photo of the the well pad, access road and reference taken using a drone (north is up).

Inspection Photos
Location Name: Maxey 33-24
Location ID: 330708



Photo 3. Ground photo taken from north of the well pad looking south down the access road.

Inspection Photos
Location Name: Maxey 33-24
Location ID: 330708



Photo 4. Tank battery overview photo taken from the southern edge of the tank battery looking west. Note: Equipment in background is not associated with oil and gas operations.

Inspection Photos
Location Name: Maxey 33-24
Location ID: 330708



Photo 5. Ground photos taken from the middle of the tank battery, Left photo is facing north and right photo is facing east.

Inspection Photos
Location Name: Maxey 33-24
Location ID: 330708



Photo 6. Ground photos taken from the middle of the tank battery, Left photo is facing south and right photo is facing west.
Note: tank battery still remains with gravel and dominated by kochia.