

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/04/2021

Submitted Date:

10/05/2021

Document Number:

699104555

FIELD INSPECTION FORM
 Loc ID 457362 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10542

Name of Operator: CUB CREEK ENERGY

Address: 200 PLAZA DRIVE SUITE 100

City: HIGHLANDS State: CO Zip: 80129

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
Rico, Trenton		trenton.rico@cub-creek.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457367	WELL	DG	09/01/2020	OW	123-47902	KNIGHT 21	DG

General Comment:

LocationOverall Good: ☐

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Frac		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Sound Walls		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 457367 Type: WELL API Number: 123-47902 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Adam Burns
 Complaint Received
 Date: 9-30-2021
 Complaint Contacted: Yes via phone
 Date: 10-1-2021 Time: 13:18PM
 Location ID # 457326
 Location name: Knight Pad
 Inspection Document # 699104545
 Complaint inspection document #699104555
 Complaint Document #402827144
 Nature of Complaint: Noise/ Vibration

Field Inspector Actions:

On 9-30-2021, I Adam Burns area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Kathy Kemper at 524 Nesting Crane Lane stated the issues were occurring outside of complainants home.
 On 10-1-2021, I attempted to make contact with the complainant who indicated that on 9-29-2021 experiencing noise and vibration at the residence.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe any unusual noise in or around location. I did not observe any changes in equipment on site. I performed a sound study, which is attached to complaint inspection. It appears to be over 65 db(C).
 At time of inspection, I spoke with Nextier Completion Solutions Frac supervisor he stated at time of complaint they were Fracking and no unusual activity was taking place and no change of equipment.
 All information reviewed and site inspection information has been submitted to the COGCC for further review.

Corrective Action: **Suggest a mitigation plan for noise/vibration per rule 423**

Date: 10/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699104556	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547267
699104557	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547268
699104558	Sound Meter Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547269