



• Photo 1 –



- Photo 2 –



- Photo 3 –



- Photo 4 –



- Photo 5 –



- Photo 6 – Open top tank spilling over on south side



- Photo 7 – Open top tank spilling over on south side



- Photo 8 – Weeds need mowing/control in former produced water pit area