

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2021

Submitted Date:

10/05/2021

Document Number:

701102024

FIELD INSPECTION FORM

| | | | | |
|---|------------------------------------|---|-------------------|---|
| Loc ID 334436 | Inspector Name: LONGWORTH, MIKE | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| Operator Information: OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1001 17TH STREET #1900 City: DENVER State: CO Zip: 80202 | | | | Findings: 30 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested |
| | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---------------------------------------|-----------------|
| COGCC, Laramie | 970-248-0497 | cogccnotifications@laramie-energy.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 301474 | WELL | PR | 06/22/2017 | OW | 077-09984 | Piceance 29-01E | PR |
| 301478 | WELL | PR | 08/11/2017 | OW | 077-09988 | Piceance 29-04M | PR |
| 301481 | WELL | PR | 06/19/2017 | OW | 077-09989 | Piceance Federal 29-01W | PR |
| 301482 | WELL | PR | 06/20/2017 | OW | 077-09990 | Piceance Federal 29-02W | PR |
| 301483 | WELL | PR | 06/15/2017 | OW | 077-09991 | Piceance Federal 29-03W | PR |
| 301484 | WELL | PR | 08/31/2020 | OW | 077-09992 | Piceance 29-05M | PR |
| 301485 | WELL | PR | 08/11/2017 | OW | 077-09993 | Piceance Federal 29-04W | PR |
| 301486 | WELL | PR | 06/19/2017 | OW | 077-09994 | Piceance 29-02E | PR |
| 301487 | WELL | PR | 08/15/2017 | OW | 077-09995 | Piceance Federal 29-05W | PR |
| 301488 | WELL | PR | 09/07/2017 | OW | 077-09996 | Piceance Federal 29-10W | PR |
| 301489 | WELL | PR | 09/10/2017 | OW | 077-09997 | Piceance Federal 29-11W | PR |
| 301490 | WELL | PR | 08/13/2017 | OW | 077-09998 | Piceance 29-07M | PR |
| 301491 | WELL | PR | 08/15/2017 | OW | 077-09999 | Piceance 29-06M | PR |
| 301493 | WELL | PR | 09/04/2017 | OW | 077-10001 | Piceance Federal 29-06W | PR |
| 301494 | WELL | PR | 09/04/2017 | OW | 077-10002 | Piceance Federal 29-08W | PR |
| 301495 | WELL | PR | 09/11/2017 | OW | 077-10003 | Piceance Federal 29-09W | PR |
| 301496 | WELL | PR | 09/13/2017 | OW | 077-10004 | Piceance Federal 29-07W | PR |
| 301497 | WELL | PR | 06/17/2017 | OW | 077-10005 | Piceance 29-03E | PR |
| 448318 | WELL | PR | 07/02/2017 | OW | 077-10328 | Piceance Federal 29-15W | PR |
| 448319 | WELL | PR | 07/02/2017 | GW | 077-10329 | Piceance Federal 29-13W | PR |
| 448320 | WELL | PR | 07/02/2017 | GW | 077-10330 | Piceance Federal 29-12W | PR |

| | | | | | | | |
|--------|------|----|------------|----|-----------|-------------------------|----|
| 448321 | WELL | PR | 07/03/2017 | GW | 077-10331 | Piceance Federal 29-16W | PR |
| 448322 | WELL | PR | 07/01/2017 | OW | 077-10332 | Piceance Federal 29-14W | PR |
| 448323 | WELL | PR | 07/14/2017 | GW | 077-10333 | Piceance Federal 29-17W | PR |

General Comment:

Routine FIU Inspection

Compliance issues identified with corrective actions and attached photos in this inspection include:

Glycol storage vessels on heated separators have no labels.

1- vessel marked 1865 gallons 4- vessels marked 2390 gallons

A follow up will be conducted to confirm corrective actions have been completed.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Glycol storage vessels on heated separators have no labels. 1- vessel marked 1865 gallons 4- vessels marked 2390 gallons | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 01/06/2022 |

| | | | |
|---------------------------|-----|-------|--|
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------|-------|--|
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------------|--|-------|
| Type: Vertical Heated Separator | # 4 | |
| Comment: | 1- vessel marked 1865 gallons 4- vessels marked 2390 gallons | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 20 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 20 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 5 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Vertical Heated Separator | # 20 | |
| Comment: | 1- vessel marked 1865 gallons 4- vessels marked 2390 gallons | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 4 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 301474 | Type: | WELL | API Number: | 077-09984 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301478 | Type: | WELL | API Number: | 077-09988 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301481 | Type: | WELL | API Number: | 077-09989 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301482 | Type: | WELL | API Number: | 077-09990 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301483 | Type: | WELL | API Number: | 077-09991 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301484 | Type: | WELL | API Number: | 077-09992 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301485 | Type: | WELL | API Number: | 077-09993 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 301486 | Type: | WELL | API Number: | 077-09994 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|------------------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 301487 | Type: | WELL | API Number: | 077-09995 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 301488 | Type: | WELL | API Number: | 077-09996 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 301489 | Type: | WELL | API Number: | 077-09997 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 301490 | Type: | WELL | API Number: | 077-09998 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 301491 | Type: | WELL | API Number: | 077-09999 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 301493 | Type: | WELL | API Number: | 077-10001 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 301494 | Type: | WELL | API Number: | 077-10002 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 301495 | Type: | WELL | API Number: | 077-10003 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 301496 | Type: | WELL | API Number: | 077-10004 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 301497 | Type: | WELL | API Number: | 077-10005 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 448318 | Type: | WELL | API Number: | 077-10328 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 448319 | Type: | WELL | API Number: | 077-10329 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 448320 | Type: | WELL | API Number: | 077-10330 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 448321 | Type: | WELL | API Number: | 077-10331 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 448322 | Type: | WELL | API Number: | 077-10332 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 448323 | Type: | WELL | API Number: | 077-10333 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | Compaction | | | | |
| Berms | | | | | | |
| | | | | Material Handling And Spill Prevention | | |
| | | Gravel | | | | |
| Ditches | | | | | | |
| | | Ditches | | | | |
| Gravel | | | | | | |
| Compaction | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 701102036 | Inspection 701102024 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547542 |