

Inspection Photos
Location Name: Iles Dome Unit 8
Location ID: 312756



Photo 1. Overview of location taken facing north. Well has been plugged. Reclamation has not begun.

