

Inspection Photos
Location Name: Iles Dome Unit 26
Location ID: 312753



Photo 1. Overview of location taken facing north.



Inspection Photos
Location Name: Iles Dome Unit 26
Location ID: 312753



Photo 2. Leak occurring at wellhead.



Photo 3. Close up of photo 2, leak occurring at wellhead.

