


**Inspection Photos**  
**Location Name: USA Shaw 19**  
**Location ID: 313419**



**Photo 1. Overview of location taken facing southwest.**



**Photo 2. No bradenhead access apparent.**



**Inspection Photos**  
**Location Name: USA Shaw 19**  
**Location ID: 313419**



**Photo 3. Stained soil on location.**



**Photo 4. Stained soil on location.**