

Inspection Photos

API: 055-06144

Operator: TABULA RASA ENERGY LLC
PERDURE PETROLEUM LLC

Inspection Date: 10/5/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 10/5/2021

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 10/5/2021

Inspection Photos



Photo 2. Facing southwest along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 10/5/2021

Inspection Photos



Photo 3. Well sign is posted at the well head and has been updated with current operator INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 10/5/2021