

Inspection Photos

API: 055-06142

Operator: TABULA RASA ENERGY LLC
PERDURE PETROLEUM LLC

Inspection Date: 10/5/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06142 | Date: 10/5/2021

Inspection Photos



Photo 1. Facing north along the access road. There are noxious weeds along the road that are dispersing seed. Seed heads should be bagged and removed. Noxious weeds need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 10/5/2021

Inspection Photos



Photo 2. Facing northeast toward the multi well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 10/5/2021

Inspection Photos



Photo 3. Well sign is posted at the well head and has been updated with current operator INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 10/5/2021

Inspection Photos



Photo 4. Facing toward the north side of the location. There are noxious weeds along the north side of the location that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 10/5/2021