

# Inspection Photos

API: 055-06285

Operator: TABULA RASA ENERGY LLC  
PERDURE PETROLEUM LLC

Inspection Date: 10/5/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the access road. Gates are installed and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06285 | Date: 10/5/2021

## Inspection Photos



**Photo 2.** Facing toward the location.



## Inspection Photos



**Photo 3.** Well sign will need to be updated to reflect current Operator.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06285 | Date: 10/5/2021