

TEP  
RGU 23-6  
Location # 335602



location



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

TEP  
RGU 23-6  
Location # 335602



location



location



TEP  
RGU 23-6  
Location # 335602



location



location



TEP  
RGU 23-6  
Location # 335602



Lack of labeling on glycol vessel



Glycol vessel dimensions



TEP  
RGU 23-6  
Location # 335602



Glycol vessel dimensions



Glycol vessel dimensions

TEP  
RGU 23-6  
Location # 335602



Debris



Debris and components to burner assembly





TEP  
RGU 23-6  
Location # 335602



**Debris**




**Unused knock out vessel**



TEP  
RGU 23-6  
Location # 335602



Debris



Unused hoses



TEP  
RGU 23-6  
Location # 335602




Unused hoses



Unused hoses



TEP  
RGU 23-6  
Location # 335602



Unused hoses



Unused hoses



TEP  
RGU 23-6  
Location # 335602



Unused hoses



Unused hoses

TEP  
RGU 23-6  
Location # 335602



Open tank burner for wildlife to enter/debris



Label is not legible



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources