

Inspection Photos
Location Name: Neff # 1
Location ID: 336482



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Neff # 1
Location ID: 336482



Photo 3 weeds have been cut around location



Photo 4 oil drum has been removed