

Inspection Photos
Location Name: Neff # 2
Location ID: 311306



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Neff # 2
Location ID: 311306



Photo 3 pump jack base

Photo 4 stained soil has been removed from flow line manifold area

Inspection Photos
Location Name: Neff # 2
Location ID: 311306



Photo 5 ECD

Photo 6 Horizontal Heated Separator

Inspection Photos
Location Name: Neff # 2
Location ID: 311306



Photo 7 TB sign

Photo 8 TB