

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2021

Submitted Date:

10/06/2021

Document Number:

696105117

FIELD INSPECTION FORMLoc ID 443200 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443201	WELL	PR	08/01/2020	OW	123-42187	Wells Ranch AA22-665	PR
443938	WELL	PR	08/01/2020	OW	123-42424	Wells Ranch AA22-670	PR
443968	WELL	PR	08/01/2020	OW	123-42438	Wells Ranch AA22-657	PR

General Comment:

This is a WELL inspection.
Well(s): 3: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Tank Battery Facility ID (480857).
Centralized Battery serves 6 Location IDs (310693, 310685, 443200, 443528, 443612, 443935).
(Well(s): 25: Producing | PR ; 1: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696105111 and/or Facility ID #480857 for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type				
Comment:	Refer to Field Inspection Report doc. #696105111 and/or Facility ID #480857 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Methanol, Corrosion Inhibitor.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	3: Wellsites.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Gas lift manifold. Iron pipe.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696105111 and/or Facility ID #480857 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	3: Wellsites. Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 3			corrective date
Comment:	3: Gas lift allocation meters. Calibration cards indicate calibration within last year. Last calibration: 09/08/2021. Active.			

Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	3: wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696105111 and/or Facility ID #480857 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	3: wellsites.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	1: Methanol pump, tank w/ drip containment. Placards. 1: Corrosion Inhibitor pump, tank w/ drip containment. Placards.		
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	3: Wellsites. Gas lift injection lines.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.471109,-104.434147
Comment:	Centralized Battery serves 1 Tank Battery Facilit ID (480857). Centralized Battery serves 6 Location IDs (310693, 310685, 443200, 443528, 443612, 443935).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 443201 Type: WELL API Number: 123-42187 Status: PR Insp. Status: PR

Producing WellComment: Producing | PR.

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 06/02/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 239 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 443938 Type: WELL API Number: 123-42424 Status: PR Insp. Status: PR

Producing WellComment: Producing | PR.

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/09/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 443968 Type: WELL API Number: 123-42438 Status: PR Insp. Status: PR

Producing WellComment: Producing | PR.

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/29/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 09/30/2021 at approximately 13:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Wells Ranch /AA22-670 Pad Location ID: 443200 Well Name(s): Wells Ranch AA22-665, Wells Ranch AA22-670, Wells Ranch AA22-657. API: 05-123-42187, 05-123-42424, 05-123-42438. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 3: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (480857). Centralized Battery serves 6 Location IDs (310693, 310685, 443200, 443528, 443612, 443935). (Well(s): 25: Producing PR ; 1: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696105111 and/or Facility ID #480857 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/06/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105118	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5549101