

Final Reclamation Inspection

October 6, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 329017

Inspection Document #: 697503303

Weld County, CO

SENE Section 36 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017




Photo 1. 2021 aerial imagery illustrates the well location and associated tank battery (red circles), and the associated access roads (red-dashed line). Plugging operations interfered with ~10 acres (orange area) of agricultural activities.

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 2. June 11, 2021 aerial imagery taken during plugging operations. Photo illustrates that prior to plugging operations, the agricultural field was prepared for agricultural activities with the evidence of furrows.

Inspection Photos

Location Name: HSR HANCOCK #8-36

Location ID: 329017



Photo 3. Drone aerial imagery taken on 10/6/2021 illustrates the ~10 acre area where plugging operations interfered with agricultural activities and also illustrates the agricultural field was prepared for agricultural activities with the evidence of furrows.



Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 4. Photo taken from the well location, facing North. Photo illustrates flowline markers.

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 5. Photo taken from the northeastern well location access road, facing East. Photo illustrates some observed vehicle rutting that the complainant stated was due to oil and gas operations.

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 6. Photo taken from the northeastern well location access road, facing East. See comments under Photo 5.



Photo 7. Photo taken from the northwestern well location access road, north of the tank battery facing North. See comments under Photo 5.

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 8. Photo taken from the tank battery, facing West. Photo illustrates unused equipment.



Photo 9. Photo taken from the tank battery, facing North. Photo illustrates unmanaged weeds.