

Final Reclamation Inspection

October 6, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 331055

Inspection Document #: 697503307

Weld County, CO

NWSW Section 18 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BERNHARDT #18-32
Location ID: 331055



Photo 1. Google Earth aerial imagery taken 6/11/2021. Photo illustrates the area of concern regarding Noble flowlines and a vault used for flowline operations that have not been removed.



Inspection Photos
Location Name: BERNHARDT #18-32
Location ID: 331055



Photo 2. Photo taken from the western exposed flowline, facing East. Photo illustrates Noble locates for flowlines that have not been removed.



Inspection Photos
Location Name: BERNHARDT #18-32
Location ID: 331055



Photo 3. Photo taken from the vault. Photo illustrates Noble locates for flowlines that have not been removed, which includes a vault.



Inspection Photos
Location Name: BERNHARDT #18-32
Location ID: 331055



Photo 4. Photo taken from the vault, facing Southeast. Photo illustrates Noble locates for flowlines that have not been removed.

