

Final Reclamation Inspection

October 6, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 445916

Inspection Document #: 697503309

Weld County, CO

NWSW Section 31 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SPILL/RELEASE POINT
Location ID: 445916



Photo 1. Photo taken from the remediation project, facing West. Photo illustrates unmanaged weeds. Note- there was native perennial vegetation observed throughout the remediation project.

Inspection Photos
Location Name: SPILL/RELEASE POINT
Location ID: 445916



Photo 2. Photo taken from the remediation project, facing North. See comments under Photo 1.