

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 1 – Pumping Units



Photo 2 – 7-62-26-2H Wellhead Sign has been posted



Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275




Photo 3 – Unmarked Riser



Photo 4 – Unmarked Riser

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 5 – Treater, Separator and ECDs – WEEDS



Photo 6 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 7 – WEEDS in Interim Reclamation Area



Photo 8 – Tank Battery

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 9 – Tank Battery Sign