

Inspection Photos
Location Name: Eleanor Arnold B 1
Location ID: 320084

Oct 7, 2021 at 12:30:51 PM
39.976357,-104.539414
Eenesburg CO 80643
United States
COGCC



Pic 1 wellhead, sign fell off of fence, needs to be replaced

Oct 7, 2021 at 12:31:00 PM
39.976357,-104.539414
Eenesburg CO 80643
United States
COGCC



Pic 2 unused equipment next to wellhead, tubing that was pulled from well recently.

Inspection Photos

Location Name: Eleanor Arnold B 1

Location ID: 320084

Oct 7, 2021 at 12:33:54 PM
39.977740,-104.537365
Keenesburg CO 80643
United States
COGCC



Pic 3 tanks, weeds unmanaged on location

Oct 7, 2021 at 12:34:15 PM
39.977634,-104.537332
Keenesburg CO 80643
United States
COGCC



Pic 4 open top tank, weeds unmanaged on location

Inspection Photos
Location Name: Eleanor Arnold B 1
Location ID: 320084

Oct 7, 2021 at 12:34:41 PM
39.977445,-104.537341
Eenesburg CO 80643
United States
COGCC



Pic 5 Separator, and gas meter run, weeds unmanaged on location