

Inspection Photos
Location Name: Shively 21-12
Location ID: 320049

Oct 7, 2021 at 2:01:19 PM
39.983038,-104.501458
Keenesburg CO 80643
United States
COGCC



Pic 1 wellhead, unused tubing next to wellhead

Oct 7, 2021 at 2:03:17 PM
39.984823,-104.499805
3001-43715 E 160th Ave
Keenesburg CO 80643
United States
COGCC



Pic 2 ECD, vertical Separator, weeds unmanaged on location

Inspection Photos
Location Name: Shively 21-12
Location ID: 320049



Pic 3 gas meter run/ trash on location



Pic 4 tanks, stained soil under load lines on tanks

Inspection Photos
Location Name: Shively 21-12
Location ID: 320049

Oct 7, 2021 at 2:04:37 PM
39.984839,-104.500325
3001-43715 E 160th Ave
Keenesburg CO 80643
United States
COGCC



Pic 5 water tank weeds unmanaged

Oct 7, 2021 at 2:05:14 PM
39.984475,-104.500662
3000-43714 E 160th Ave
Keenesburg CO 80643
United States
COGCC



Pic 6 weeds unmanaged