

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402835653

Date Received:
10/08/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------|-------|--|
| - | | inspection@sginterests.com |

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203168

Inspection Date: 09/24/2021

FIR Submit Date: 09/28/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 428197

Location Name: Eck 12-90-1 Number: 428197 County: _____

Qtrqr: Lot 1 Sec: 1 Twp: 12S Range: 90W Meridian: 6

Latitude: 39.048170 Longitude: -107.390720

FACILITY - API Number: 05-051-00 Facility ID: 428197

Facility Name: Eck 12-90-1 Number: 428197

Qtrqr: Lot 1 Sec: 1 Twp: 12S Range: 90W Meridian: 6

Latitude: 39.048170 Longitude: -107.390720

CORRECTIVE ACTIONS:

1 CA# 156263

Corrective Action: Comply with Rule 1002.f.(2) and install or repair BMPs in accordance with good engineering practices.

Date: 10/05/2021

Response: CA COMPLETED

Date of Completion: 10/05/2021

Operator Comment: SG has completed the interim reclamation on this location. Soils were seeded and straw was tracked on the interim reclamation areas to stabilize the soils. Plesae see attached photo documentation of seeded and tracked straw in the interim reclamation areas. Erosion control bmp's (straw wattles) were placed in a perpendicular orientation in the outflow channel to prevent and control any potential sediment form leaving the location. These bmp's (straw wattles) are a temporary sediment control measure. As a long term solution, this outflow channel will also be partially lined with rock within a week to prevent and control sediment from leaving the location. SG is also continuing work on the inlet protection.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Arnett

Signed: _____

Title: Reg Permitting

Date: 10/8/2021 11:24:08 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---|
| 402835904 | Soil Stabilization With Seed and Straw Tracking |

Total Attach: 1 Files