

# Inspection Photos

API: 071-07742

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/7/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/7/2021

## Inspection Photos



**Photo 1.** Facing southwest toward the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/7/2021

## Inspection Photos



**Photo 2.** Facing southwest toward the location which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/7/2021

## Inspection Photos



**Photo 3.** The electric utilities remain and the cable are unsecured.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/7/2021

## Inspection Photos



**Photo 4.** Facing north at the location. There are undesirable weeds shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/7/2021

## Inspection Photos



**Photo 5.** Facing east toward the surrounding undisturbed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/7/2021