

Inspection Photos  
Operator: Simcoe  
API: 067-08833  
Date: 10/6/2021



Photo 1. View of project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with smooth brome, western wheatgrass, and rubber rabbitbrush.





Photo 3. View of silt trap full of sediment in the northwestern project area.





Photo 4. View of erosional tunneling approx. 4ft wide and over 6ft deep in the eastern project area.





Photo 5. View of reference area comprised of sagebrush shrubland and pinyon-juniper woodland with James galleta, western wheatgrass, matte penstemon, and sticky rabbitbrush.