

Inspection Photos
Operator: Simcoe
API: 067-09562
Date: 10/6/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass and smooth brome.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of erosional channel approx. 2ft wide and 18 inches deep in the northwestern edge of the project area. (main photo facing upslope within the project area, and inset facing downstream and outside of the project area.



Photo 5. View of reference area comprised of sagebrush shrubland and pinyon-juniper woodland with James galleta, western wheatgrass, matte penstemon, and sticky rabbitbrush.