

Inspection Photos
Operator: Simcoe
API: 067-07465
Date: 10/6/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern project area facing northward. Revegetation is progressing with western wheatgrass, intermediate wheatgrass, rubber rabbitbrush, and smooth brome.



Photo 3. View of the southern fill slope from the southwestern corner facing eastward.



Photo 4. View of cable debris in the southern project area.



Photo 5. View of reference area comprised of sagebrush shrubland and pinyon-juniper woodland with James galleta, western wheatgrass, matte penstemon, and sticky rabbitbrush.