

**Inspection Photos**  
**Location Name: Siefken 11-30H-7-61**  
**Location ID: 424135**



**Photo 1 – Pumping Unit**



**Photo 2 – Gas Engine Exhaust – Weeds and Stained Soil**

**Inspection Photos**  
**Location Name: Siefken 11-30H-7-61**  
**Location ID: 424135**



**Photo 3 – Stained Soil at Gas Engine**

**Photo 4 – Stained Soil at Wellhead**

**Inspection Photos**  
**Location Name: Siefken 11-30H-7-61**  
**Location ID: 424135**



Colorado Oil and Gas Conservation Commission  
40.55203, -104.25807, 4739.9ft, 275°  
10/05/2021 13:38:13



Colorado Oil and Gas Conservation Commission  
40.552, -104.25805, 4745.0ft, 263°  
10/05/2021 13:38:16

**Photo 5 – Tank Battery**

**Photo 6 – Tank Battery Sign**

**Inspection Photos**  
**Location Name: Siefken 11-30H-7-61**  
**Location ID: 424135**



Colorado Oil and Gas Conservation Commission  
40.55199, -104.2579, 4758.0ft, 71°  
10/05/2021 13:38:35

**Photo 7 – Separator**



Colorado Oil and Gas Conservation Commission  
40.55199, -104.2579, 4758.4ft, 167°  
10/05/2021 13:38:37

**Photo 8 – ECD and Flare**

**Inspection Photos**  
**Location Name: Siefken 11-30H-7-61**  
**Location ID: 424135**



**Photo 9 – Weeds at Flare base**



**Photo 10 – Weeds ECD base**