

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2021

Submitted Date:

10/10/2021

Document Number:

696105127

FIELD INSPECTION FORM

Loc ID 448379 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448380	WELL	PR	07/01/2020	OW	123-43877	Wells Ranch State AA33-718	PR
448382	WELL	PR	07/01/2020	OW	123-43879	Wells Ranch State AA33-735	PR
448524	WELL	PR	12/01/2020	OW	123-43917	Wells Ranch State AA33-725	PR

General Comment:

This is a WELL inspection.
Well(s): 3: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Tank Battery Facility ID (480892).
Centralized Battery serves 3 Location IDs (448379, 448376, 448378).
(Well(s): 10: Producing | PR).

Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.

Location				
Lease Road:				
	Type Access			
	comment: Adequate			
Corrective Action:			Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type CONTAINERS			
	Comment: Methanol, Corrosion Inhibitor.			
Corrective Action:			Date:	
	Type WELLHEAD			
	Comment: 3: Wellsites.			
Corrective Action:			Date:	
	Type			
	Comment: Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.			
Corrective Action:			Date:	
Emergency Contact Number:				
	Comment:			
	Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type WELLHEAD			
	Comment: 3: Wellsites. Iron panel.			
Corrective Action:			Date:	
	Type			
	Comment: Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.			
Corrective Action:			Date:	
	Type LOCATION			
	Comment: Barbed wire.			
Corrective Action:			Date:	
	Type OTHER			
	Comment: Gas lift manifold. Iron pipe.			
Corrective Action:			Date:	

Equipment:			corrective date
Type: Other	# 3		
Comment:	3: Wellsites. Gas lift injection lines.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	3: Gas lift allocation meters. Calibration cards indicate calibration within last year. Last calibration: 08/11/2021. Active.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	1: Corrosion Inhibitor pump, tank w/ drip containment. Placards. 1: Methanol pump, tank w/ drip containment. Placards.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	3: Wellsites.		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	3: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.466436,-104.436071
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (480892). Centralized Battery serves 3 Location IDs (448379, 448376, 448378). Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 448380 Type: WELL API Number: 123-43877 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/02/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 448382 Type: WELL API Number: 123-43879 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/02/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 448524 Type: WELL API Number: 123-43917 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/02/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 14 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 10/05/2021 at approximately 15:52 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Wells Ranch State /AA33-735 Multi Location ID: 448379 Well Name(s): Wells Ranch State AA33-718, Wells Ranch State AA33-735, Wells Ranch State AA33-725. API: 05-123-43877, 05-123-43879, 05-123-43917. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 3: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (480892). Centralized Battery serves 3 Location IDs (448379, 448376, 448378). (Well(s): 10: Producing PR).</p> <p>Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/10/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105129	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5550901