

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19SWSW

Location ID: 335005



Photo #5016 from entrance to location.



Photo #5017 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19SWSW

Location ID: 335005



Photo #5018 from entrance to location.



Photo #5019 No battery sign located at the tank battery.



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19SWSW

Location ID: 335005



Photo #5020 Glycol storage tank missing required information.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources