

**Inspection Photos**  
**Location Name: Litzenberger Pad**  
**Location ID: 444819**



Colorado Oil and Gas Conservation Commission  
40.24273, -105.01518, 1526.4m  
Sep 30, 2021 2:25:23 PM

**Photo 1 loc pic**



Colorado Oil and Gas Conservation Commission  
40.24273, -105.01518, 1526.4m  
Sep 30, 2021 2:25:27 PM

**Photo 2 loc pic**

**Inspection Photos**  
**Location Name: Litzenberger Pad**  
**Location ID: 444819**



**Photo 3 loc pic**



**Photo 4 loc pic**

**Inspection Photos**  
**Location Name: Litzenberger Pad**  
**Location ID: 444819**



Colorado Oil and Gas Conservation Commission  
40.24238, -105.02116, 1536.0m  
Sep 30, 2021 2:25:52 PM

**Photo 5 loc pic**



Colorado Oil and Gas Conservation Commission  
40.24234, -105.02115, 1535.8m  
Sep 30, 2021 2:26:01 PM

**Photo 6 Stained soil under motor oil storage tanks**



**Inspection Photos**  
**Location Name: Litzenberger Pad**  
**Location ID: 444819**



**Photo 7 Stained soil in and around Crude oil concrete vault.**



**Photo 8 2" risers not LOTO**

**Inspection Photos**  
**Location Name: Litzenberger Pad**  
**Location ID: 444819**



**Photo 9 Risers not LOTO.**



**Photo 10 Meter house does not have calibration card accessible.**



**Inspection Photos**  
**Location Name: Litzenberger Pad**  
**Location ID: 444819**



Colorado Oil and Gas Conservation Commission  
40.24208, -105.02166, 1537.6m  
Sep 30, 2021 2:27:55 PM

**Photo 11 VRU's**



Colorado Oil and Gas Conservation Commission  
40.24207, -105.02168, 1538.5m  
Sep 30, 2021 2:28:00 PM

**Photo 12 ECD's Not lit at time of inspection.**

**Inspection Photos**  
**Location Name: Litzenberger Pad**  
**Location ID: 444819**



Colorado Oil and Gas Conservation Commission  
40.24204, -105.02219, 1544.4m  
Sep 30, 2021 2:29:30 PM

**Photo 13 VRU's**



Colorado Oil and Gas Conservation Commission  
40.24208, -105.02214, 1539.5m  
Sep 30, 2021 2:32:00 PM

**Photo 14 TNK BTRY PRV's on all tanks venting gas at time of inspection.**