

Final Reclamation Inspection

October 6, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 329842

Inspection Document #: 697503320

Weld County, CO

NENW Section 36 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE #36-317
Location ID: 329842



Photo 1. Drone aerial photo taken from the well location, facing North. Photo illustrates the well location and well location access road are not reflective of reference crop areas. An approximate 20' x 30' area at the well location and portions of the well location access road are evident.



Inspection Photos

Location Name: STATE #36-317

Location ID: 329842



Photo 2. Drone aerial photo taken from the well location, facing West. Photo illustrates reference area vegetative conditions.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503320

Inspection Photos
Location Name: STATE #36-317
Location ID: 329842



Photo 3. Photo taken from the associated offsite tank battery, facing West. Photo illustrates the tank battery is reflective of reference crop areas.

