

Final Reclamation Inspection

October 6, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 329023

Inspection Document #: 697503324

Weld County, CO

NWNW Section 36 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE #36-4E
Location ID: 329023



Photo 1. Drone aerial photo taken from the well location, facing North. Photo illustrates the well location and well location access road are reflective of reference crop areas. The associated offsite tank battery (red circle) is not reflective of reference areas.



Inspection Photos
Location Name: STATE #36-4E
Location ID: 329023



Photo 2. Drone aerial photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: STATE #36-4E
Location ID: 329023



Photo 3. Drone aerial photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: STATE #36-4E
Location ID: 329023



Photo 4. Drone aerial photo taken from the well location, facing West. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503324

Inspection Photos
Location Name: STATE #36-4E
Location ID: 329023



Photo 5. Photo taken from the associated offsite tank battery, facing West. Photo illustrates the tank battery consists mostly of annual, weedy vegetation.



Inspection Photos
Location Name: STATE #36-4E
Location ID: 329023



Photo 6. Photo taken from the associated offsite tank battery, facing Southwest. Photo illustrates the reference area appears to be native perennial vegetation consisting mostly of sand dropseed but could also be active cropland depending on the year.

