

Inspection Photos
Location Name: Speaker 1-2731-8-61
Location ID: 424603



Photo 1 – Pumping Units/Wellheads



Photo 2 – Flare and Gas Meter – Missing Calibration Card

Inspection Photos
Location Name: Speaker 1-2731-8-61
Location ID: 424603




Photo 3 – Missing Calibration Card



Photo 4 – East Separator

Inspection Photos
Location Name: Speaker 1-2731-8-61
Location ID: 424603



Colorado Oil and Gas Conservation Commission
40.63893, -104.18763, 4923.5ft, 201
10/06/2021 12:03:21

Photo 5 – Tank Battery



Colorado Oil and Gas Conservation Commission
40.63893, -104.18805, 4933.5ft, 201
10/06/2021 12:03:45

Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Speaker 1-2731-8-61
Location ID: 424603



Photo 7 – West Heater Treater and ECD



Photo 8 – Compressor

Inspection Photos
Location Name: Speaker 1-2731-8-61
Location ID: 424603



Photo 9 – Wildlife Netting is in disrepair