

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 1 – Pumping Unit – Weeds



Photo 2 – Pumping Unit – Weeds



Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 3 – Pumping Unit – Weeds



Photo 4 – Separators

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 5 – Separators – Weeds



Photo 6 – Tank Battery Sign



Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 7 – Weeds



Photo 8 – Tank Battery

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 9 – Missing NPFA and Content Labels




Photo 10 – Capacity Label missing

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 11 – Tank Battery Weeds



Photo 12 – Tank Battery Weeds

