

Inspection Photos

Location Name: WELLS RANCH USX /AA27-66-1HN

Location #: 432507



Photo #1

WELLS RANCH USX /AA27-66-1HN pad 4: Wellsites

3: Producing | PR

1: Temporarily Abandoned | TA



Photo #2

Wells Ranch USX AA27-69-1HN (05-123-37138)

Wellsite

Temporarily Abandoned | TA

Inspection Photos

Location Name: WELLS RANCH USX /AA27-66-1HN

Location #: 432507



Photo #3

Wells Ranch USX AA27-68-1HN (05-123-37139)

Wellsite

Producing | PR



Photo #4

Wells Ranch USX AA27-67-1HN (05-123-37141)

Wellsite

Producing | PR

Inspection Photos

Location Name: WELLS RANCH USX /AA27-66-1HN

Location #: 432507



Photo #5

Wells Ranch USX AA27-66-1HN (05-123-37142)

Wellsite

Producing | PR



Photo #6

WELLS RANCH USX /AA27-66-1HN pad 4: Wellsites

Gas Lift Manifolds

Active