

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/30/2021

Submitted Date:

10/05/2021

Document Number:

701102022

FIELD INSPECTION FORM

| | | | | |
|---|------------------------------------|---|-------------------|---|
| Loc ID 452797 | Inspector Name: LONGWORTH, MIKE | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| Operator Information: OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1001 17TH STREET #1900 City: DENVER State: CO Zip: 80202 | | | | Findings: 24 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested |
| | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---------------------------------------|-----------------|
| COGCC, Laramie | 970-248-0497 | cogccnotifications@laramie-energy.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 452788 | WELL | PR | 01/27/2019 | OG | 077-10508 | BCU 0993-21-05E | PR |
| 452789 | WELL | PR | 02/28/2019 | OG | 077-10509 | BCU 0993-21-01E | PR |
| 452790 | WELL | PR | 02/15/2019 | OG | 077-10510 | BCU 0993-21-02E | PR |
| 452791 | WELL | PR | 03/01/2019 | OW | 077-10511 | BCU 0993-21-04W | PR |
| 452792 | WELL | PR | 02/09/2019 | OG | 077-10512 | BCU 0993-21-05W | PR |
| 452793 | WELL | PR | 01/02/2019 | OG | 077-10513 | BCU 0993-21-09E | PR |
| 452794 | WELL | PR | 01/28/2019 | OG | 077-10514 | BCU 0993-21-07E | PR |
| 452795 | WELL | PR | 03/01/2019 | OG | 077-10515 | BCU 0993-21-01W | PR |
| 452796 | WELL | PR | 01/02/2019 | OG | 077-10516 | BCU 0993-21-08E | PR |
| 452798 | WELL | PR | 03/04/2019 | OG | 077-10517 | BCU 0993-21-03W | PR |
| 452799 | WELL | PR | 03/01/2019 | OG | 077-10518 | BCU 0993-21-04E | PR |
| 452800 | WELL | PR | 01/28/2019 | OG | 077-10519 | BCU 0993-21-06E | PR |
| 452801 | WELL | PR | 01/09/2019 | OG | 077-10520 | BCU 0993-21-09W | PR |
| 452802 | WELL | PR | 01/07/2019 | OG | 077-10521 | BCU 0993-21-10W | PR |
| 452803 | WELL | PR | 01/04/2019 | OG | 077-10522 | BCU 0993-21-10E | PR |
| 452804 | WELL | PR | 03/02/2019 | OG | 077-10523 | BCU 0993-21-02W | PR |
| 452805 | WELL | PR | 02/03/2019 | OG | 077-10524 | BCU 0993-21-06W | PR |
| 452821 | WELL | PR | 01/10/2019 | OW | 077-10525 | BCU 0993-21-08W | PR |
| 452831 | WELL | PR | 02/02/2019 | OG | 077-10526 | BCU 0993-21-07W | PR |

General Comment:

Routine FIU Inspection

Compliance issues identified with corrective actions and attached photos in this inspection include:

Glycol storage vessels on heated separators have no labels.

3-5 well unit and 1-4 well unit with Glycol tanks approximately 60"x48"x199" = 2470.9 gallons

A follow up will be conducted to confirm corrective actions have been completed.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|--|-------|------------|
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Glycol storage vessels on heated separators have no labels. 3-5 well unit and 1-4 well unit with Glycol tanks approximately 60"x48"x199" = 2470.9 gallons | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 01/06/2022 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|-----|-------------|
| Comment: | 911 | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|-------|-------|--|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|--|------|--------|--|--|
| Type | Area | Volume | | |
| In Containment: | No | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Equipment:

| | | | |
|-----------------------|------|-------|-----------------|
| Type: Bird Protectors | # 5 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 19 | | |
| Comment: | | | |

| | | | |
|---------------------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 19 | | |
| Comment: | 3-5 well unit and 1-4 well unit with Glycol tanks appoximately 60"x48"x199" = 2470.9 gallons | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 19 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 8 | 400 BBLS | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452788 | Type: | WELL | API Number: | 077-10508 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452789 | Type: | WELL | API Number: | 077-10509 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452790 | Type: | WELL | API Number: | 077-10510 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452791 | Type: | WELL | API Number: | 077-10511 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452792 | Type: | WELL | API Number: | 077-10512 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452793 | Type: | WELL | API Number: | 077-10513 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452794 | Type: | WELL | API Number: | 077-10514 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452795 | Type: | WELL | API Number: | 077-10515 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|------------------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452796 | Type: | WELL | API Number: | 077-10516 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452798 | Type: | WELL | API Number: | 077-10517 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452799 | Type: | WELL | API Number: | 077-10518 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452800 | Type: | WELL | API Number: | 077-10519 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452801 | Type: | WELL | API Number: | 077-10520 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452802 | Type: | WELL | API Number: | 077-10521 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452803 | Type: | WELL | API Number: | 077-10522 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452804 | Type: | WELL | API Number: | 077-10523 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452805 | Type: | WELL | API Number: | 077-10524 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452821 | Type: | WELL | API Number: | 077-10525 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452831 | Type: | WELL | API Number: | 077-10526 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Seeding | | | | | | |
| | | Gravel | | | | |
| Ditches | | | | | | |
| Compaction | | | | | | |
| Gravel | | | | | | |
| | | | | Material Handling And Spill Prevention | | |
| | | Ditches | | | | |
| Berms | | | | | | |
| | | Compaction | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 402831841 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547543 |
| 701102034 | Inspection 701102022 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5547540 |