

Inspection Photos

10/08/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 439173

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 439173



October 8, 2021
39.45476552N 107.80994702W

Photo 1: Photo taken from the Location entrance, facing west. Photo shows signage at the Location entrance is missing.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 439173



Photo 2: Photos show the sediment traps on the northeast and northwest corners of the pad; BMP has not been maintained in proper functioning condition; a berm has been constructed at trap and is preventing proper stormwater runoff and discharge from the pad. Drain pipe also not properly laid out and secured.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 439173



Photo 3: Photos taken from the cut slopes. Photos provide examples showing control measures to protect/stabilize the cut slopes of the location are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 439173



Photo 4: Photos provide example of Undesirable and Noxious Plant species observed established on the Location.